

MONUMENT RECORD
State of Indiana - County of Monroe

Section: 20

Township: 7 North

Range: 1 East



Corner ID: Polk I-13

Monument Description & Remarks: 3" Forest Service monument with cap 1 ft above ground.

Survey Sign 5ft above ground at pt. B

References On File: Matthew Cooper survey, USDA (2005) on file in Records Office cabinet S, envelope 285


RECOVERY TIE DRAWING
Field Book 38 Page No. 71





- A - 3" Forest Service monument
- B - S 25° W 10.11' to Survey Sign
in 10" Quaky Aspen
- C - N 65° W 48.75' to MAG nail
in 5" Red Oak
- D - N 23° E 89.20' to MAG nail
in 12" White Pine

Not To Scale
Compass Bearing Magnetic North

I, Kevin P. Enright, Monroe County Surveyor, hereby certify that this document was prepared under my direction in accordance with the provisions of section 36-2-12-1 of the Indiana Code; and the above data is given under my hand and seal this 8th day of January, 2007.





Administered by the Monroe County Surveyor Review Board

Date: 2/20/2007 DB

CERTIFIED LAND CORNER RESTORATION

State of Indiana }
County of Monroe } ss.

I Andrew J. Sobiech, do hereby certify that on the 13 day of May, 19 74,
I found evidence of the 1/4 Section corner of Section 20 - 21
Township 7 North, Range 1 East, Second Principal Meridian, as described
hereon; and that from this evidence I established a new monument and accessories as described hereon to per-
petuate the original location of this corner:

Description of original monument and accessories and subsequent restorations:


Original monument was	Subsequent survey by Buskirk, Co. Surveyor, filed
a wood post set in 1814:	in Monroe County.
Original bearing trees:	His bearing trees were:
W. Oak B. Oak	Hickory Sycamore
10" 10"	3" 6"
S 72° E S 63° W	N 72° E S 65° W
14 lks 18 lks	10 1/2 lks 28 lks

Description of corner evidence found:

Found stone 5"x4" 10" above ground at the Northeast corner of an open field.
The stone is marked with + on top.

Description of monument and accessories I established to perpetuate the original location of this corner:
I left the stone in place and made the following new witnesses:

4"x4" Post	Scarlett Oak	Scarlett Oak	Scarlett Oak
East	10" DBH	12" DBH	11" DBH
4.9 feet	N 30° E	N 44° W	S 48° W
	15.0 feet	12.2 feet	13.2 feet



● = Corner monument restored
□ =

Field Assistant
~~Resident witnesses~~ Henry Deaton - Tom Getz - U.S.F.S.

Dated at Brownstown Indiana, this 7 day of May, 19 75.

Signature Andrew J. Sobiech Title Land Surveyor
(County Surveyor, Registered Land Surveyor, or other duly authorized official)

Surveyors Registration No. S-0143


Office of _____ County of _____
I hereby certify that the within instrument was filed in this office for record
on the _____ day of _____ 19_____, and was filed in Book
No. _____ Page No. _____ of County Records.

Signature _____ Title _____

Index No. N-9
(Alphabetical - Numerical)LAND CORNER RECORD
(RECTANGULAR SURVEYS)R9-7150-4 (Rev. 6/13/67)
GPO 806-924T. 7N, S. 1E, Mer. 2nd N.F. Hoosier County Monroe State Ind.
Corner common to sections 16, 17, 20 and 21

EXISTING SURVEYS

Original Government Survey	Original Evidence Found
Year surveyed _____	Year of search <u>1980</u> By _____
Original monument _____ (Wood post, stone, pile of stones, pipe, etc.)	Monument found _____
Bearing Trees	Original Bearing Trees Found
Species _____	Species _____
Diameter _____	Diameter _____
Bearing _____	Bearing _____
Distance _____	Distance _____
Subsequent Corner Restoration	Evidence of Subsequent Corner Restoration Found
Year surveyed _____ By _____	Year of search _____ By _____
Where filed or recorded _____	_____
Monument _____ (Original, concrete post, iron rod, etc.)	_____
_____	_____
Bearing Trees, Reference Objects	Bearing Trees, Reference Objects
Species _____	_____
Diameter _____	_____
Bearing _____	_____
Distance _____	_____



Sketch

○ Corner ■ F.S. Land

At time of search:

1. Did you have the record description?
Yes _____ No _____2. How was search area located?
Pacing, chaining, photos, maps,
etc. _____

3. Man hours spent in search _____

4. Do you think additional search might
recover evidence? Yes _____ No _____5. Signature J. C. [unclear]

Relation of Evidence to Record Features Along Section Lines

Section line to sections	Object	Record distance	Measured distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Other Evidence

Describe evidence of use and occupation such as roads, fences, clearings, timber cutting lines, plantations, etc.. Cite source of testimony if any.

Location of stone found by information from corner cards, stone is in a very bad condition, replaced with monument, 2 1/2" galvanized pipe filled with concrete, with brass cap on top. Position of stone checked by land line survey in April 1980. Cap is not stamped at this time.

Perpetuation Record

Monument and accessories established. Include brief description of area.


B. T.	B. T.
Aspen	Aspen
8"	6"
S 2° W	N 79° W
10.17'	13.74'

Certified corner restoration certificate prepared:	Yes _____ No _____
Filed in county records at _____	Date _____ County Document No. _____
Identified on aerial photo No. _____	Which is filed at _____

Index No.
 (Alphabetical - Numerical)LAND CORNER RECORD
(RECTANGULAR SURVEYS)R9-7150-4 (Rev. 6/13/67)
GPO 806-924T. 7 N R. 1 E. 2nd Mer. N.F. Hoosier County Monroe State Ind.
Sec. Cor. Corner common to sections 17, 16, 20 and 21

EXISTING SURVEYS

Original Government Survey	Original Evidence Found
Year surveyed _____ Original monument _____ (Wood post, stone, pile of stones, pipe, etc.)	Year of search _____ By _____ Monument found _____
Bearing Trees Species _____ Diameter _____ Bearing _____ Distance _____	Original Bearing Trees Found Species _____ Diameter _____ Bearing _____ Distance _____
Subsequent Corner Restoration Year surveyed _____ By _____ Where filed or recorded _____ Monument _____ (Original, concrete post, iron rod, etc.)	Evidence of Subsequent Corner Restoration Found Year of search <u>3-1980</u> By <u>Tim Cummings</u> <u>Sandstone 3"X10"X7" stone is</u> <u>in several pieces couldn't find</u> <u>any scribing</u>
Bearing Trees, Reference Objects Species _____ Diameter _____ Bearing _____ Distance _____	Bearing Trees, Reference Objects _____ _____ _____ _____



Sketch

O Corner ☒ F.S. Land

At time of search:

1. Did you have the record description?
Yes _____ No ☒2. How was search area located?
Pacing, chaining, photos, maps,
etc. _____3. Man hours spent in search 30 min.4. Do you think additional search might
recover evidence? Yes _____ No _____5. Signature Tim Cummings

Relation of Evidence to Record Features Along Section Lines

Section line to sections _____
Object _____
Record distance _____
Measured distance _____

Other Evidence

Describe evidence of use and occupation such as roads, fences, clearings, timber cutting lines, plantations, etc.. Cite source of testimony if any.

Stone is broken off flush with ground. fence
mound running E-W-N. old F.S. location tag under
leaves by stone, clump of young white oak saplings
about 70' W. possibly from ~~camp~~ W.O. called for
in 1964 Corner Card. 30' S.E. of logging trail in
broomsedge field. Aspen Sassafras stand app. 10'
South of field.

Perpetuation Record

Monument and accessories established. Include brief description of area. _____

Certified corner restoration certificate prepared: Yes _____ No _____
Filed in county records at _____ Date _____ County Document No. _____
Identified on aerial photo No. _____ Which is filed at _____